Troubleshooting Guide

TB60

diesel - gasoline - LPG

PRO66

diesel - gasoline - LPG

Snorkel

OmniQuip

Snorkel INTERNATIONAL


An ISO 9001 Registered Company

P/N 0082801
May, 1998

P.O. Box 1160 • St. Joseph, MO 64502-1160
1-800-255-0317 • Fax: 816-360-9379
www.snorkelusa.com

MidWestTech | Snorkel TB60, PRO66 Telescopic Boom Lift Troubleshooting Guide | Public... Order the manual at mid-west-tech.com >

Chart 1



MidWestTech | Snorkel TB60, PRO66 Telescopic Boom Lift Troubleshooting Guide | Public... Order the manual at mid-west-tech.com >

Chart 2





Chart 3



MidWestTech | Snorkel TB60, PRO66 Telescopic Boom Lift Troubleshooting Guide | Public... Order the manual at mid-west-tech.com >

Chart 4




Chart 5






Chart 6




MidWestTech | Snorkel TB60, PRO66 Telescopic Boom Lift Troubleshooting Guide | Public... Order the manual at mid-west-tech.com >

Two wheels turn faster than the other two (4 wheel drive)




Step 1

Step 2




MidWestTech | Snorkel TB60, PRO66 Telescopic Boom Lift Troubleshooting Guide | Public... Order the manual at mid-west-tech.com >




Step 3

Step 4



MidWestTech | Snorkel TB60, PRO66 Telescopic Boom Lift Troubleshooting Guide | Public... Order the manual at mid-west-tech.com >



Order the manual at mid-west-tech.com >