
snorkel

# TB120
# T120



CE

## REPAIR PARTS MANUAL

Manufactured 07-05 and after

Models TB120/T120
Replaces 0191909 March 2014

Part Number 0192646
October 2016

MidWestTech | Snorkel TB120, T120 Telescopic Boom Lift Repair Parts Manual | Publicatio... Order the manual at mid-west-tech.com >

| Item | Part No. | Name | Qty | Uom |
|---|---|---|---|---|
| 25 | 0190986 | DRIVE SPEED CUTOUT SWITCH SUB ASSEMBLY | | REF |
| 26 | 0191011 | DECAL TERM STRIP VERT 6 | 1 | EA |
| 27 | 0191179 | MANIFOLD SUB ASSEMBLY | | REF |
| 28 | 0191458 | HYDRAULIC OIL RETURN FILTER | | REF |
| 29 | 0191680 | WLDMT, TURNTABLE | 1 | EA |
| 30 | 0191756 | HYDRAULIC OIL RESERVOIR ASSEMBLY | | REF |
| 31 | 0191787 | WLDMT MNT LIMIT SW | 1 | EA |
| 32 | 0191789 | BOOM LIFT SWITCH ASSEMBLY | 1 | EA |
| 33 | 0191830 | FUEL TANK INSTALL-T3 TB100J/120/126J | 1 | EA |
| 34 | 0191971 | WLDMT BRKT JUNCTION BOX | 1 | EA |
| 35 | 0192037 | BOOM CALIBRATION SWITCH ASSEMBLY | | REF |
| 36 | 0192054 | PLATE EMS MNTG | 1 | EA |
| 37 | 0192197 | NON PROPORTIONAL VALVE ASSEMBLY (complete with fittings and hardware) | | REF |
| 38 | 0192587 | LIFT SWING COUNTERWEIGHT INSTALLATION | 1 | EA |
| 39 | 0192590 | PROPORTIONAL CONTROL VALVE ASSEMBLY COMPLETE ( WITH FITTINGS AND HARDWARE) | | REF |
| 40 | 0192652 | ENGINE KUBOTA V2403-CR TIER4B | | REF |
| 41 | 0192656 | BRKT ENGINE MOUNT KU T4F | 2 | EA |
| 42 | 0192658 | WLDMT RADIATOR SUPPORT | 2 | EA |
| 43 | 0192689 | FUEL SYSTEM ASSEMBLY KUBOTA V2403 T4F | 1 | EA |
| 44 | 0192705 | GROUND CONTROL PANEL ASSEMBLY TIER 4F TB126J | | REF |
| 45 | 0192706 | ASSY JNCTN BOX T4F | | REF |



MidWestTech | Snorkel TB120, T120 Telescopic Boom Lift Repair Parts Manual | Publicatio... Order the manual at mid-west-tech.com >

| Item | Part No. | Name | Qty | Uom |
|---|---|---|---|---|
| 23 | KIT ITEM | CST RING - (NOT SOLD SEPARATELY) | 1 | EA |
| 24 | KIT ITEM | WEAR RING - (NOT SOLD SEPARATELY) | 2 | EA |
| 25 | KIT ITEM | O-RING - (NOT SOLD SEPARATELY) | 1 | EA |
| 26 | KIT ITEM | U-RING - (NOT SOLD SEPARATELY) | 1 | EA |
| 27 | KIT ITEM | BACK-UP - (NOT SOLD SEPARATELY) | 1 | EA |
| 28 | KIT ITEM | WEAR RING - (NOT SOLD SEPARATELY) | 3 | EA |
| 29 | KIT ITEM | WIPER - (NOT SOLD SEPARATELY) | 1 | EA |




MidWestTech | Snorkel TB120, T120 Telescopic Boom Lift Repair Parts Manual | Publicatio... Order the manual at mid-west-tech.com >

| Item | Part No. | Name | Qty | Uom |
|---|---|---|---|---|
| 88 | 3090019 | TUBE FLEXGUARD .250 ID | 9.2 FT | FT |
| 91 | HH0518F08CZ016 | HHCS .313-18 F GR8 C 1.000 | 2 | EA |
| 92 | 0192037 | BOOM CALIBRATION SWITCH ASSEMBLY | 1 | REF |
| 93 | FLW0010STCZ | WASHER FLAT #10 STL C | 4 | EA |
| 94 | 3040469 | RELAY SPDT 12V 30AMP SONG | 1 | EA |
| 95 | 0072951 | GUIDE BAR | 1 | EA |
| 97 | 5093002 | CLP CUSH .562 VINYL COATED | 2 | EA |
| 98 | 5093008 | CLP CUSH 1.06 VINYL COATED | 1 | EA |
| 99 | 3050096 | SURGE PROTECTOR 12V | 1 | EA |
| 100 | 0192042 | WIRE ASSEMBLY EMS VPL | 1 | REF |
| 101 | 0192043 | WIRE ASSY EMS PRIMARY ANGLE | 1 | REF |
| 102 | 0192044 | WIRE ASSY EMS PRIMARY LGTH | 1 | REF |
| 103 | 0192022 | WIRE ASSY EMS BU LGTH SENSOR EMS2 | 1 | REF |
| 104 | 0192023 | WIRE ASSY EMS BU ANGLE SENSOREMS2 | 1 | REF |
| 105 | 0191996 | RESISTOR WIRE TB120 PRIMARY | 1 | EA |
| 106 | 0191997 | RESISTOR WIRE TB120 BACKUP | 1 | EA |
| 21 | 056067-010 | Nut, HexNut DIN934 M10 8.0 Zin | 2 | EA |
| 82 | 5560609 | SCR TRHD 10-24 .500 | 2 | EA |
| 22 | 970489 | CAPSCREW, 3/8-16 X 1.5" LG HEX HD GR5 | 2 | EA |
| 44 | 970029 | BLT HEXHD .250-20 .75 GR5-Z/P | 4 | EA |
| 47 | PNNA | SCR 118-32 X .50 LG RDHD | 6 | EA |
| 73 | PNNA | WSHR FLAT 118 | 6 | EA |
| 50 | 0110596 | WIRE 12 RIOIR81 10 | 2 | EA |



MidWestTech | Snorkel TB120, T120 Telescopic Boom Lift Repair Parts Manual | Publicatio... Order the manual at mid-west-tech.com >





Order the manual at mid-west-tech.com >