A TEREX BRAND

Parts Manual

Serial Number Range

GS-2046

from SN GS4613D-101 to GS4616D-5029

GS-2646

from SN GS46D-5030 to GS46D-9637

GS-3246

Part No. 1267431GT

Rev A7

November 2018

Order the manual at mid-west-tech.com >

Table of Contents

This manual is updated frequently. If you have a printed manual, you can keep it up to date by downloading new figures from the Genie website at www.genielift.com. For the most up-to-date parts information, visit the Parts Lookup System on the Genie website at www.genielift.com.

How to Read Your Serial Number....3
Parts Stocking List....7
How to Order Parts....8
Service Parts Fax Order Form....9

Electronic Version

Click on any page number to view the figure.

001 Parts Stocking List
001.1 Parts Stocking List....10

100 Decals
101.1 Word Decals, GS-2046, Battery Side, ANSI & Australia....12
102.1 Word Decals, GS-2046, Ground Control Side, ANSI and Australia....14
103.1 Word Decals, GS-2046, Platform, ANSI....16
104.1 Word Decals, GS-2046, Platform, Australia....18
105.1 Word Decals, GS-2646, Battery Side, ANSI & Australia....20
106.1 Word Decals, GS-2646, Ground Control Side, ANSI and Australia....22
107.1 Word Decals, GS-2646, Platform, ANSI....24
108.1 Word Decals, GS-2646, Platform, Australia....26
109.1 Word Decals, GS-3246, Battery Side, ANSI & Australia....28
110.1 Word Decals, GS-3246, Ground Control Side, ANSI and Australia....30
111.1 Word Decals, GS-3246, Platform, ANSI....32
112.1 Word Decals, GS-3246, Platform, Australia....34
113.1 Symbol Decals, GS-2046, Battery Side, ANSI & CE..36
114.1 Symbol Decals, GS-2046, Ground Control Side, ANSI and CE....38
115.1 Symbol Decals, GS-2046, Platform, ANSI....40
116.1 Symbol Decals, GS-2046, Platform, CE....42
117.1 Symbol Decals, GS-2646, Battery Side, ANSI & CE..44
118.1 Symbol Decals, GS-2646, Ground Control Side, ANSI and CE....46
119.1 Symbol Decals, GS-2646, Platform, ANSI....48
120.1 Symbol Decals, GS-2646, Platform, CE....50
121.1 Symbol Decals, GS-3246, Battery Side, ANSI & CE..52
122.1 Symbol Decals, GS-3246, Ground Control Side, ANSI and CE....54
123.1 Symbol Decals, GS-3246, Platform, ANSI....56
124.1 Symbol Decals, GS-3246, Platform, CE....58

200 Drive Chassis Components
201.1 Steer Linkage and Wheels....60
202.1 Non-steer Axle Installation....62
203.1 Level Sensor Installation....64
204.1 Pothole Protection Assembly....66
205.1 Battery Pack Module....68
206.1 Battery Charger....70
207.1 Power Unit Module....72
208.1 Ground Controls....74
209.1 Electrical Wiring....76
210.1 Power Cables....78
211.1 Function Manifold and Accumulator Components....80

300 Scissor Components
301.1 Scissor Assembly Installation....82
302.1 Scissor Assembly, GS-2046....84
303.1 Scissor Assembly, GS-2646....86
304.1 Scissor Assembly, GS-3246....88

400 Platform Components
401.1 Platform Components....90
402.1 Power to Platform....92
403.1 Platform Controls....94
404.1 Joystick Controller....96

500 Hydraulic Components
501.1 Hydraulic Components....98
502.1 Function Manifold....100
503.1 Brake Release Hand Pump Manifold....102
504.1 Hydraulic Power Unit, All Models....104
505.1 Lift Cylinder Assembly, All Models....106
506.1 Hydraulic Hoses and Fittings....108

600 Accessories
601.1 Alarm, Horn and Flashing Beacons....110
602.1 Air Line to Platform....112
603.1 Platform Work Light....114
604.1 Voltage Inverter....116
605.1 Pipe Cradle Assembly....118
606.1 Panel Carrier Assembly, GS2046, GS-2646 (ANSI/CSA models)....120


MidWestTech | Terex Genie GS-2046, GS-2646, GS-3246 Scissor Lift Parts Manual | Publi... Order the manual at mid-west-tech.com >

700 Platform Overload Components
701.1 Platform Overload.....122


Indices
Part Number Index.....124
Part Description Index.....127

Cross References
Fittings Cross Reference.....132

MidWestTech | Terex Genie GS-2046, GS-2646, GS-3246 Scissor Lift Parts Manual | Publi... Order the manual at mid-west-tech.com >



MidWestTech | Terex Genie GS-2046, GS-2646, GS-3246 Scissor Lift Parts Manual | Publi... Order the manual at mid-west-tech.com >



MidWestTech | Terex Genie GS-2046, GS-2646, GS-3246 Scissor Lift Parts Manual | Publi... Order the manual at mid-west-tech.com >

Fitting Cross References (Continued)

Genie PN	Parker PN	Description
48892	6 C6LO-S	ELBOW,90°,SWIVEL NUT ORFS
48893	6 F5OHAO-S	UNION,STRAIGHT THREAD
48894	6 WLO-WLNL-S	UNION,BULKHEAD,ORFS
48895	DT-370-MSMO-5	VALVE,CHECK
48896	6 JLO-S	UNION,TEE,ORFS
48897	DT-750-MSMS-5	VALVE,CHECK
48898	DT-750-MOMS-5	VALVE,CHECK
48899	DT-620-MOMS-5	VALVE,CHECK
48900	4-6 F5OLO-SW.039	CONNECTOR,STRAIGHT THREAD TO ORFS, W/.039 ORI
48902	16-1 ACE4G-S	ELBOW,90° LONG,FEMALE PIPE TO STRAIGHT THREAD
48903	1 FF-S	NIPPLE,PIPE
48904	4 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48905	4 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48906	4 R5OLO-S	RUN TEE,STRAIGHT THREAD
48907	4 V5OLO-S	ELBOW,45°,STRAIGHT THREAD TO ORFS
48908	4 R6LO-S	RUN TEE,SWIVEL NUT,ORFS
48909	4 WJJLO-WLNL-S	RUN TEE, BULKHEAD,ORFS
48910	4 GTX-S W.030	CONNECTOR,FEMALE PIPE TO FLARE TUBE
48911	4-6 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48912	4-6 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48913	4-6 F5OLO-SW.030	CONNECTOR,STRAIGHT THREAD TO ORFS, W/.030 ORI
48914	4-8 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48915	6 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48916	6 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48917	6 FF5OLO-S	CONNECTOR,LONG,STRAIGHT THREAD TO ORFS
48918	6 R5OLO-S	RUN TEE,STRAIGHT THREAD
48919	6 S5OLO-S	BRANCH TEE,STRAIGHT THREAD TO ORFS
48920	6 V5OLO-S	ELBOW,45°,STRAIGHT THREAD TO ORFS
48921	6 FLO-S	CONNECTOR,MALE PIPE TO ORFS
48922	6-6 FLO-S	CONNECTOR,MALE PIPE TO ORFS
48923	6 P5ON-S	PLUG,STRAIGHT THREAD
48925	6 WELO-S	UNION,90° BULKHEAD,ORFS
48926	6-4 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48927	6-4 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48928	6-4 V5OLO-S	ELBOW,45°,STRAIGHT THREAD TO ORFS
48929	6-8 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48930	6-8 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48931	6-10 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48932	8 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48933	8 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48934	8 FF5OLD-S	CONNECTOR,LONG,STRAIGHT THREAD TO ORFS
48935	8 R5OLO-S	RUN TEE,STRAIGHT THREAD
48936	8 S5OLO-S	BRANCH TEE,STRAIGHT THREAD TO ORFS
48937	8 V5OLO-S	ELBOW,45°,STRAIGHT THREAD TO ORFS

Genie PN	Parker PN	Description
48938	8 R6LO-S	RUN TEE,SWIVEL NUT,ORFS
48939	8 S6LO-S	BRANCH TEE,SWIVEL NUT TO ORFS
48940	8 WJJLO-WLNL-S	RUN TEE, BULKHEAD,ORFS
48941	8-4 TRLO-S	REDUCER,TUBE END TO SWIVEL,ORFS
48942	8-6 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48943	8-6 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48944	8-8 FLO-S	CONNECTOR,MALE PIPE TO ORFS
48945	8 FTX-S	CONNECTOR,MALE PIPE TO FLARE TUBE
48946	8-10 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48947	8-12 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48948	8-12 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48949	8-16 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48950	10 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48951	10 CC5OLO-S	ELBOW,90° LONG,STRAIGHT THREAD TO ORFS
48952	10 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48953	10 R5OLO-S	RUN TEE,STRAIGHT THREAD
48954	10 S5OLO-S	BRANCH TEE,STRAIGHT THREAD TO ORFS
48955	10 R6LO-S	RUN TEE,SWIVEL NUT,ORFS
48956	10-4 TRLO-BL-S	REDUCER,TUBE END TO SWIVEL,ORFS
48957	10-6 TRLO-BL-S	REDUCER,TUBE END TO SWIVEL,ORFS
48958	10-12 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48959	12 C5OLO-S	ELBOW,90°,STRAIGHT THREAD TO ORFS
48960	12 F5OLO-S	CONNECTOR,STRAIGHT THREAD TO ORFS
48961	12 R5OLO-S	RUN TEE,STRAIGHT THREAD
48962	12 S5OLO-S	BRANCH TEE,STRAIGHT THREAD TO ORFS
48963	12 V5OLO-S	ELBOW,45°,STRAIGHT THREAD TO ORFS
48964	12 R6LO-S	RUN TEE,SWIVEL NUT,ORFS
48965	12 CLO-S	ELBOW,90° MALE PIPE TO ORFS
48966	12 FLO-S	CONNECTOR,MALE PIPE TO ORFS
48967	12 JLO-S	UNION TEE,ORFS
48968	12 WLO-WLNL-S	UNION,BULKHEAD,ORFS
48969	12 WJJLO-WLNL-S	RUN TEE, BULKHEAD,ORFS
48970	12 WELO-WLNL-S	UNION,90° BULKHEAD W/NUT,ORFS

MidWestTech | Terex Genie GS-2046, GS-2646, GS-3246 Scissor Lift Parts Manual | Publi... Order the manual at mid-west-tech.com >