snorkel

SR1054



REPAIR PARTS MANUAL

Part Number 159-0025-000
November 2022

Order the manual at mid-west-tech.com >

Item	Part No.	Name	Qty	Uom
-	PNNA	BOOM ASSEMBLY 9M - FR03		EA
1	REF.DWG 055.005.000-SR1054-SR9244-FR03	FIXED BOOM ASSEMBLY FR03 9M	1	EA
2	REF.DWG 055.007.000-SR1054-SR9244-FR03	EXTENSION CYLINDER FR03 9 METRES	1	EA
3	REF.DWG 055.006.000-SR1054-SR9244-FR03	EXTENSION ASSEMBLY FR03 9M	1	EA
4	REF.DWG 055.009.000-SR1054-SR9244-FR03	LINKAGE CRANK ASSEMBLY AND CONNECTING ROD ASSEMBLY LINKAGE BRAN FR03	1	EA

MidWestTech | Snorkel SR1054 Telehandler Repair Parts Manual | Publication 159-0025-0... Order the manual at mid-west-tech.com >


Item	Part No.	Name	Qty	Uom
-	PNNA	OPTIONAL - AIR CONDITIONING		EA
1	REF. TAB. 090.001.001-SR1054-SR9244	AIR CONDITIONING COMPRESSOR	1	EA
2	REF. TAB. 090.001.002-SR1054-SR9244	CABIN AIR CONDITIONING KIT	1	EA

MidWestTech | Snorkel SR1054 Telehandler Repair Parts Manual | Publication 159-0025-0... Order the manual at mid-west-tech.com >

Item	Part No.	Name	Qty	Uom
19	SN-220140111	PILOT 1/4" L400 EYE1/4"/EYE1/4"	2	EA
20	SN-220140116	PILOT 1/4" L1300 F90L10/EYE1/4G - 0°	1	EA
21	SN-220140111	PILOT 1/4" L400 EYE1/4"/EYE1/4"	2	EA
22	SN-220580108	M4K MEGAFLEX 5/8" L4800 F90L18/F90L18 - 270°	2	EA
23	SN-220580108	M4K MEGAFLEX 5/8" L4800 F90L18/F90L18 - 270°	2	EA
24	SN-220122405	HOSE M4KMTF 1/2 L2440 F 13/16O-F9013/16O	1	EA
25	SN-220123803	HOSE M4KMTF 1/2 L3800 F90 13/16O-F90 1O	1	EA
26	SN-220580106	M4K MEGAFLEX 5/8" L2500 F90L18/F90L18-0°	2	EA
27	SN-220580106	M4K MEGAFLEX 5/8" L2500 F90L18/F90L18-0°	2	EA
28	SN-220123501	PIPE M4KMTF 1/2 L3500 M 1O-F90 13/16O	2	EA
29	SN-220123501	PIPE M4KMTF 1/2 L3500 M 1O-F90 13/16O	2	EA
30	SN-220121006	M4KMTF 1/2 L1000 F 13/16O-M 1O HOSE	1	EA
31	SN-220121511	M4KMTF 1/2 L1500 F 13/16O-F 1O HOSE	1	EA
32	SN-220140107	PILOT 1/4" L800 FD10L/F9010L	1	EA
33	SN-220140116	PILOT 1/4" L1300 F90L10/EYE1/4G - 0°	1	EA
34	SN-220380112	PILOT 3/8" L1100 F90L12/FDL12	1	EA
35	SN-220163002	MICROHOSE L800	1	EA
36	SN-220380105	M3K 3/8" L2000 F9012L/FD12L	1	EA
37	SN-220380130	M3K 3/8" L2300 F90L12/FDL12 - 0°	1	EA
38	SN-220380107	M3K 3/8" L1400 F9012L/F9012L - 0°	1	EA

MidWestTech | Snorkel SR1054 Telehandler Repair Parts Manual | Publication 159-0025-0... Order the manual at mid-west-tech.com >


ELECTRICAL



MidWestTech | Snorkel SR1054 Telehandler Repair Parts Manual | Publication 159-0025-0... Order the manual at mid-west-tech.com >

11		SN-720000197	1
12		SN-720000200 (from 09/2023) (before it was SN-720000184)	1
13		SN- 720000258(from 03/2025)	1
14		SN-850100064(from 07/2022)	2
15		SN-850100065(from 07/2022)	1
16		SN-725190001	1
17		SN-850100063(from 07/2022)	1
18		SN-850100069 (from 07/2022)	4
19		SN-850100070(from 07/2022)	2
20		SN-720000171 (only withoptional 6-way manual diverter valve)	1

MidWestTech | Snorkel SR1054 Telehandler Repair Parts Manual | Publication 159-0025-0... Order the manual at mid-west-tech.com >



Order the manual at mid-west-tech.com >