snorkel

SR9244



REPAIR PARTS MANUAL

Part Number 159-0026-000
January 2019

Order the manual at mid-west-tech.com >

Item	Part No.	Name	Qty	Uom
-	PNNA	MAIN TRANSMISSION ASSEMBLY - FR04		EA
1	REF. TAB. 040.001.000-SR1054-SR9244	CARRARO 26.25 FRONT AXLE KIT	1	EA
2	REF. TAB. 040.002.000-SR1054-SR9244	CARRARO 26.25 REAR AXLE KIT	1	EA
3	REF. TAB. 040.003.000-SR1054-SR9244	CLASSIC CARDAN SHAFT KIT	1	EA
4	REF. TAB. 030.000.000-SR1054-SR9244	DANFOSS ENGINE KIT H1B160K1_3B	1	EA
5	REF. TAB. 030.001.000-SR1054-SR9244	DANFOSS PUMP KIT H1P078 (IF 100KW - 74KW)	1	EA
5.1	REF. TAB. 030.002.000-SR1054-SR9244	DANFOSS PUMP KIT H1P078 (IF 55KW)	1	EA
6	REF. TAB. 040.004.000-SR1054-SR9244	COMPLETE INDUSTRIAL WHEEL KIT 20" CAMSO	1	EA

MidWestTech | Snorkel SR9244 Telehandler Repair Parts Manual | Publication 159-0026-0... Order the manual at mid-west-tech.com >


Item	Part No.	Name	Qty	Uom
-	PNNA	BOOM ASSEMBLY 9M - FR03		EA
1	REF.DWG 055.005.000-SR1054-SR9244-FR03	FIXED BOOM ASSEMBLY FR03 9M	1	EA
2	REF.DWG 055.007.000-SR1054-SR9244-FR03	EXTENSION CYLINDER FR03 9 METRES	1	EA
3	REF.DWG 055.006.000-SR1054-SR9244-FR03	EXTENSION ASSEMBLY FR03 9M	1	EA
4	REF.DWG 055.009.000-SR1054-SR9244-FR03	LINKAGE CRANK ASSEMBLY AND CONNECTING ROD ASSEMBLY LINKAGE BRAN FR03	1	EA

MidWestTech | Snorkel SR9244 Telehandler Repair Parts Manual | Publication 159-0026-0... Order the manual at mid-west-tech.com >

Item	Part No.	Name	Qty	Uom
19	SN-220140111	PILOT 1/4" L400 EYE1/4"/EYE1/4"	2	EA
20	SN-220140105	PILOT 1/4" L1300 OCCHIO1/4G/OCCHIO1/4G	1	EA
21	SN-220140111	PILOT 1/4" L400 EYE1/4"/EYE1/4"	2	EA
22-23	SN-220580108	M4K MEGAFLEX 5/8" L4800 F90L18/F90L18 - 270°	2	EA
24	SN-220123803	HOSE M4KMTF 1/2 L3800 F90 13/16O-F90 1O	1	EA
25	SN-220122405	HOSE M4KMTF 1/2 L2440 F 13/16O-F9013/16O	1	EA
26-27	SN-220580105	M4K 5/8" L3200 F90L18/F90L18 - 0°	2	EA
28-29	SN-220120129	M4K 1/2" L2580 F90L15/F90L15 - 0°	2	EA
30-31	SN-220120140	M4K MTF 1/2" L1300 MD1"ORFS/FD15L HOSE	2	EA
32-33	SN-220380135	M4K 3/8" L5000 EYE 1/2"G/EYE 1/2" G-0° HOSE	2	EA
34	SN-220121006	M4KMTF 1/2 L1000 F 13/16O-M 1O HOSE	1	EA
35	SN-220121511	M4KMTF 1/2 L1500 F 13/16O-F 1O HOSE	1	EA
36	SN-220140107	PILOT 1/4" L800 FD10L/F9010L	1	EA
37	SN-220140137	PILOT 1/4" L1800 F90L10/F90L10 - 180°	1	EA
38	SN-220380112	PILOT 3/8" L1100 F90L12/FDL12	1	EA
39	SN-220163002	MICROHOSE L800	1	EA
40	SN-220380105	M3K 3/8" L2000 F9012L/FD12L	1	EA
41	SN-220380136	M3K 3/8" L2500 F90L12/OCCHIOM18 - 0° HOSE	1	EA
42	SN-220380107	M3K 3/8" L1400 F9012L/F9012L - 0°	1	EA
43	SN-220380108	M3K 3/8" L1800 F9012L/F9012L - 180°	1	EA

MidWestTech | Snorkel SR9244 Telehandler Repair Parts Manual | Publication 159-0026-0... Order the manual at mid-west-tech.com >


ELECTRICAL



MidWestTech | Snorkel SR9244 Telehandler Repair Parts Manual | Publication 159-0026-0... Order the manual at mid-west-tech.com >

11		SN-720000197	1
12		SN-720000200 (from 09/2023) (before it was SN-720000184)	1
13		SN- 720000258(from 03/2025)	1
14		SN-850100064(from 07/2022)	2
15		SN-850100065(from 07/2022)	1
16		SN-725190001	1
17		SN-850100063(from 07/2022)	1
18		SN-850100069 (from 07/2022)	4
19		SN-850100070(from 07/2022)	2
20		SN-720000171 (only withoptional 6-way manual diverter valve)	1

MidWestTech | Snorkel SR9244 Telehandler Repair Parts Manual | Publication 159-0026-0... Order the manual at mid-west-tech.com >



Order the manual at mid-west-tech.com >