snorkel

SR1745



REPAIR PARTS MANUAL

Part Number 159-0043-000
November 2022

Order the manual at mid-west-tech.com >

Item	Part No.	Name	Qty	Uom
-	PNNA	DEUTZ ENGINE ASSEMBLY (IF 55KW)		EA
1	REF.TAB. 010.001.003-SR1054-SR9244	DEUTZ ENGINE TCD3.6 L4 - 55KW - STAGE_V	1	EA
2	REF.TAB. 010.003.000-SR1054-SR9244	AIR FILTER ASSEMBLY TCD 3,6 STAGE_IV	1	EA
3	REF.TAB. 010.004.001-SR1054-SR9244	EXCHANGER ASSEMBLY TCD3,6 55KW STAGE V	1	EA
4	REF.TAB. 010.005.002-SR1054-SR9244	CONTROL UNIT ASSEMBLY TCD3,6 STAGE_V	1	EA
5	REF.TAB. 010.006.002-SR1054-SR9244	DIESEL FILTER ASSEMBLY TCD3,6	1	EA
	PNNA	DEUTZ TCD3,6 55 KW - STAGE V		EA
6	REF.TAB. 010.007.000-SR1054-SR9244	WATER TANK ASSEMBLY	1	EA
7	SN-T28018150	EXHAUST BRACKET	1	EA
8	SN-601080110	DOC PIPE D.80 WITH DEUTZ FLEX TCD3.6	1	EA

MidWestTech | Snorkel SR1745 Telehandler Repair Parts Manual | Publication 159-0043-0... Order the manual at mid-west-tech.com >


Item	Part No.	Name	Qty	Uom
-	29601-100 A	GRAPPLE W/SHOE CLAMP 9660 OPTION ASSEMBLY		EA
1	29459-100	WLDMNT, GRAPPLE	1	EA
2	27462-000	WLDMT ARM UPPER POLE GRPLR ORG	2	EA
3	29571-000	WLDMT LOWER ARM ORG	2	EA
4	29569-000	WLDMT SHOE CLAMP ORG	2	EA
5	14865-000	FORK TINES 2-1/4 X 6 X 60 2P	2	EA
6	27483-000	ASSY, GRAPPLER ARM MANIFOLD	1	EA
7	27481-000	ASSY, LOWER CYLINDER	2	EA
8	29396-000	ASSY, UPPER CYLINDER	2	EA
9	27493-000	WIRE ASSEMBLY GRAPPLER VALVE	1	EA
10	29154-000	Sleeve- Roller ORG	2	EA
11	27498-000	TUBE ARM ROLLER BLK	2	EA
12	13754-012	MACH BUSHING 1-1/4 X 18 GA	4	EA
13	13749-016	BUSHING 1.25 ID X 1 LG 20FDU16	8	EA
14	13702-016	BRG, GARMAX GM2024-016	4	EA
15	13704-016	BRG, GARMAX GM2832-016	4	EA
16	27473-000	PIN WELDMENT 1.50 X 9.34	2	EA
17	27474-000	PIN WELDMENT 1.50 X 6.19	2	EA
18	27475-000	PIN WELDMENT 1.75 X 9.37	2	EA
19	27476-000	PIN WELDMENT 1.25 X 6.19	4	EA
20	27477-000	PIN WELDMENT 2.00 X 9.25	2	EA
21	27478-000	PIN WELDMENT 1.25 X 4.38	4	EA
22	11712-001	FTNG ELBOW 90 BH -04MFS-04MFS	4	EA
23	11702-002	FITTING ELBOW 90 -06MBA-04MFS	4	EA
24	11700-001	FTG, STR, 4MORFS-MORB	4	EA

MidWestTech | Snorkel SR1745 Telehandler Repair Parts Manual | Publication 159-0043-0... Order the manual at mid-west-tech.com >

REF. TAB. 080.000.004-SR1054-SR9244 2-51
REF. TAB. 080.000.005-SR1054-SR9244 2-51
REF. TAB. 080.000.006 2-52
REF. TAB. 080.000.008-SR1054-SR9244 2-51
REF. TAB. 080.000.009 2-52
REF. TAB. 080.000.010 2-52
REF. TAB. 080.000.010-SR1054-SR9244 2-51
REF. TAB. 090.001.001-SR1054-SR9244 5-2
REF. TAB. 090.001.002-SR1054-SR9244 5-2
REF.TAB. 010.001.003-SR1054-SR9244 2-33
REF.TAB. 010.003.000-SR1054-SR9244 2-33
REF.TAB. 010.004.001-SR1054-SR9244 2-33
REF.TAB. 010.005.002-SR1054-SR9244 2-33
REF.TAB. 010.006.002-SR1054-SR9244 2-33
REF.TAB. 010.007.000-SR1054-SR9244 2-33
SN-090.010.000-SR1054-SR9244 5-27
SN-090.013.001-SR1054-SR9244 5-27
SN-100040401 2-65, 2-66, 4-4, 4-50
SN-100120701 2-130
SN-100121001 2-65, 2-66, 4-50, 4-51
SN-100180001 2-19
SN-101050501 2-40, 2-96, 2-97
SN-101061001 2-40, 2-70, 2-130, 2-134, 2-144, 2-145
SN-101061002 2-105, 2-112, 2-141
SN-101061003 2-59, 3-36
SN-101080801 2-40, 2-58, 2-68, 2-86, 2-87, 2-118, 4-17, 5-10, 5-11
SN-101101001 2-40, 2-70, 2-96, 2-97, 2-98, 2-105, 2-129, 2-144, 2-145, 5-10, 5-11, 5-14, 5-14
SN-101121501 2-129, 5-32
SN-101141001 2-140
SN-101201001 5-16
SN-101202201 2-70, 2-103
SN-102001201 2-73
SN-103000101 2-43, 2-44
SN-104000101 2-43, 2-44
SN-10ME05336D47 4-6
SN-111160501 4-9
SN-111200801 2-70, 2-143
SN-113000602 2-43, 2-44
SN-113005000 2-43, 2-44, 2-45, 2-46, 2-47, 2-48, 2-75, 2-76, 2-77
SN-120052501 5-10, 5-11
SN-120061201 2-89, 2-90, 2-92
SN-120062001 2-40
SN-120062501 2-91, 2-92, 2-93
SN-120063001 2-40
SN-120067001 2-59
SN-120080801 2-53
SN-120081101 2-40, 5-3
SN-120082001 2-86, 2-87
SN-120082501 2-49
SN-120083001 2-53, 2-134, 5-3, 5-22
SN-120083501 2-40
SN-120084001 2-130

MidWestTech | Snorkel SR1745 Telehandler Repair Parts Manual | Publication 159-0043-0... Order the manual at mid-west-tech.com >


ELECTRICAL



MidWestTech | Snorkel SR1745 Telehandler Repair Parts Manual | Publication 159-0043-0... Order the manual at mid-west-tech.com >

11		SN-720000197	1
12		SN-720000200 (from 09/2023) (before it was SN-720000184)	1
13		SN- 720000258(from 03/2025)	1
14		SN-850100064(from 07/2022)	2
15		SN-850100065(from 07/2022)	1
16		SN-725190001	1
17		SN-850100063(from 07/2022)	1
18		SN-850100069 (from 07/2022)	4
19		SN-850100070(from 07/2022)	2
20		SN-720000171 (only withoptional 6-way manual diverter valve)	1

MidWestTech | Snorkel SR1745 Telehandler Repair Parts Manual | Publication 159-0043-0... Order the manual at mid-west-tech.com >



Order the manual at mid-west-tech.com >