
POWER RAKE

S/N 925100101 & Above

Service Manual



MELROE
INGERSOLL-RAND

6900891 (10-99)

© Melroe Company 1999
Printed in U.S.A.

MidWestTech | Bobcat Power Rake Attachment Service Manual | Publication 6900891_10_... Order the manual at mid-west-tech.com >

ALPHABETICAL INDEX

CASTER BEARINGS 10–30–1

DRIVE CHAIN 10–30–1
DRUM BEARINGS 10–30–1

ELECTRICAL SCHEMATIC 10–40–1

GLOSSARY OF HYDRAULIC SYMBOLS FOR ATTACHMENTS 10–40–1

HYDRAULIC CONTROL VALVE 10–20–1
HYDRAULIC CYLINDER 10–20–1
HYDRAULIC MOTOR 10–20–1
HYDRAULIC SCHEMATIC 10–40–1

IDENTIFICATION iii

LUBRICATION 10–10–1

POWER RAKE CONVERSION MATRIX 10–40–1

RE–HARDSURFACING ROLLER TEETH (Early Models) 10–30–1

REPLACING CARBIDE ROLLER TEETH (Later Models) 10–30–1

SERIAL NUMBER LOCATION iii
SPECIFICATIONS 10–40–1

MidWestTech | Bobcat Power Rake Attachment Service Manual | Publication 6900891_10_... Order the manual at mid-west-tech.com >

CONTENTS

SERIAL NUMBER LOCATION iii
IDENTIFICATION iii
PREVENTIVE MAINTENANCE 10–10–1
HYDRAULIC SYSTEM 10–20–1
MAIN FRAME 10–30–1
SPECIFICATIONS AND SCHEMATICS 10–40–1

CALIFORNIA
PROPOSITION 65 WARNING
Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects and other reproductive harm.

MidWestTech | Bobcat Power Rake Attachment Service Manual | Publication 6900891_10_... Order the manual at mid-west-tech.com >