1822, 1844, 2022, 2044 and 2055

Cotton Pickers

SERVICE MANUAL

8-62645

CASE IH AGRICULTURE

MidWestTech | Case 1822, 1844, 2022, 2044, 2055 Cotton Picker Service Manual | Publication 8-27745

Order the manual at mid-west-tech.com >

1822, 1844, 2022, 2044 and 2055 Cotton Picker Service Manual

Table of Contents

Description	Section No.	Form No.
General	**Tab 1**	
Loctite Product Chart		8-98900
Engine Specifications - D466	1020	8-62491
Engines - D466 Navistor (International)	**Tab 2**	
Engine Troubleshooting	2010	8-62231
Engine Tune-Up - D466	2015	8-27421
Engine Removal and Installation	2020	8-62190
Cylinder Head and Valve Train	2030	8-27181
Cylinder Block	2040	8-27211
Lubrication System	2060	8-27191
Turbocharger - T04B	2265	8-20190
Turbocharger Failure Analysis - All Engines	2565	9-78235
Cooling System	2070	8-27231
Air Induction and Exhaust System	2090	8-62510
- 6-590 Case		
Engine Specifications - 6-590	2401	8-26063
Cylinder Head and Valve Train	2415	8-26073
Cylinder Block	2425	8-26084
Lubrication System	2445	8-26093
After Cooler	2545	8-26120
Cooling System	2455	8-26103
Turbocharger 2465		8-26110
- 6-830 Case		
Engine Specifications	2403	8-28423
Cylinder Head and Valve Train	2415	8-28432
Cylinder Block	2425	8-28442
Lubrication System	2445	8-28452
Cooling System	2455	8-28462
Turbocharger	2465	8-28470
Fuel System - D466 Navistor Engines	**Tab 3**	
Fuel System and Filters	3010	8-27241
Fuel Injection Pump - Robert Bosch Type MW	3020	8-27251
Fuel Injectors	3030	8-27261
- 6-590 Case Engine		
Fuel System and Filters	3410	8-26131
Fuel Injection Pump (CAV)	3411	8-97711
Fuel Injectors	3413	8-26152
- 6-830 Case Engine		
Fuel System and Filters	3410	8-28480
Fuel Injection Pump	3412	8-28492
Fuel Injectors	3413	8-28501

Reprinted

CASE CORPORATION

Rac 8-62645

Copyright © 1992 Case Company

Printed in U.S.A.
August, 1992

MidWestTech | Case 1822, 1844, 2022, 2044, 2055 Cotton Picker Service Manual | Publica... Order the manual at mid-west-tech.com >

1822, 1844, 2022, 2044 and 2055 Cotton Picker Service Manual

Table of Contents

Description	Section No.	Form No.
Electrical	**Tab 4**	
Electrical Wiring Schematics and Troubleshooting - 2022 & 2044	4001	8-97551
Electrical Wiring Schematics and Troubleshooting - 2055	4002	8-98001
Electrical System Troubleshooting - 1822 & 1844	4010	8-62030
Alternator - Bosch	4004	8-91792
Instrument Cluster Troubleshooting	4011	8-62520
Starting Motor - Nippondensa	4011	8-95970
Digital Tachometer Troubleshooting	4012	8-62040
Compactor Troubleshooting	4013	8-62050
Monitor Troubleshooting	4014	8-62061
Cotton Picker Electrical Wiring Diagram - 1822 & 1844	4020	8-62070
Cab Electrical Wiring Diagram - 1822 & 1844	4025	8-62360
Electro-Hydraulic Valve Wiring Diagram - 1822 & 1844	4030	8-62080
Battery Servicing and Testing	4235	8-20291
Starter Motor - 1822 & 1844	4040	8-62530
Alternator System - Motorola	4060	8-62170
Neutral Start Switches	4070	8-62271
Steering	**Tab 5**	
Steering Axle - 2055	5003	8-99060
Steering System Testing	5010	8-62420
Steering Column and Hand Pump - Ross	5020	8-62430
Steering Column and Hand Pump - Eaton	5021	8-98040
Steering Cylinder	5030	8-62440
Steering Axle -1822, 1844, 2022 & 2044	5040	8-62450
Power Train	**Tab 6**	
Hydrostatic Propulsion Troubleshooting	6010	8-62380
Foot-N-Inch Valve	6015	8-62550
Hydrostatic Drive Pump Removal and Installation	6017	8-62280
Hydrostatic Drive Pump	6018	7-34620
Hydrostatic Drive Motor	6030	8-62471
Transmission and Drum Drive Assembly, Removal and Installation	6035	8-62250
Transmission - 1822, 1844, 2022 & 2044	6040	8-62391
Transmission - 2055	6041	8-99050
Drum Drive Assembly - 1822, 1844, 2022 & 2044	6050	8-62091
Drum Drive Assembly - 2055	6051	8-82770
Final Drive and Pinion Assembly	6060	8-62201
Brakes	**Tab 7**	
Service and Parking Brake -1822, 1844, 2022 & 2044	7010	8-62211
Service and Parking Brake - 2055	7011	8-99120
Brake Valve and Cylinders	7020	8-62240

Rac 8-62545

Printed in U.S.A.
August, 1992

MidWestTech | Case 1822, 1844, 2022, 2044, 2055 Cotton Picker Service Manual | Publica... Order the manual at mid-west-tech.com >

1822, 1844, 2022, 2044 and 2055 Cotton Picker
Service Manual


Table of Contents


Description	Section No.	Form No.
Hydraulic	Tab 8	
Hydraulic System Schematics and Troubleshooting - 2022 & 2044	8001	8-97560
Hydraulic System Schematics and Troubleshooting - 2055	8002	8-98010
Hydraulic System Troubleshooting - 1822 & 1844	8010	8-62100
Hydraulic System Testing - 1822 & 1844	8020	8-62620
Hydraulic Oil Filters	8030	8-62261
Hydraulic Pump Removal and Installation	8037	8-62290
Hydraulic Pump and Compensator	8040	8-62480
Electro-Hydraulic Valves	8050	8-62111
Electro-Hydraulic Manifold Valve - 2055	8051	8-99020
Hydraulic Valves, Cylinders and Motor	8060	8-62181
Destroke Solenoid Valve	8061	8-98770
Height Control Valves and Cylinders - 2055 Model	8062	8-99110
Accessories	Tab 9	
Servicing the Air Conditioner Compressor Sanden Model SD 508 HD	9000	7-35200
Air Conditioner Troubleshooting	9001	7-35210
Air Conditioner System Gauges and Testing	9002	7-37680
Air Conditioner System Service, Recovery, Evacuation and Recharging	9003	7-34860
Air Conditioning Components Service for Systems with Sanden Compressor	9004	7-34890
Air Conditioner Compressor Removal and Installation on Navistar Engines	9030	8-62331
Servicing the York Air Conditioner Compressor and System Components	9040	8-62320
Servicing the Cab Blower	9050	8-62300
Operators Seat	9060	8-62310
Fan Assembly	9070	8-62221
Moistener System	9075	8-62571
Basket Assembly	9077	8-62580
Picker Drum Removal and Installation	9080	8-62120
Picker Drum Removal and Installation - 2055 Model	9081	8-99190
Chain Driven Picker Drum Service	9090	8-62130
Gear Driven Picker Drum Service	9091	8-97850
Picker Bar and Spindle Lubrication System	9092	8-98610
Drum Gearboxes and Input Drive Shafts - 2055 Model	9093	8-99100
How It Works	Tab 10	
Digital Tachometer	10030	8-62400
Compactor Control	10050	8-62630
Drum Operation	10070	8-62140

Rac 8-62645

Printed in U.S.A.
August, 1992

MidWestTech | Case 1822, 1844, 2022, 2044, 2055 Cotton Picker Service Manual | Publica... Order the manual at mid-west-tech.com >





MidWestTech | Case 1822, 1844, 2022, 2044, 2055 Cotton Picker Service Manual | Publication 8-27745
Order the manual at mid-west-tech.com >