SERVICE MANUAL

VL5060 / VL5080 / VL5090
VL6040 / VL6050 / VL6060 / VL6070 / VL6080 / VL6090
VM3080 / VM3090 / VM4090
VN2090

Grape Harvesters

Print No. 84189523B

NEW HOLLAND AGRICULTURE

MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6070, VL6080, VL6090, VM3080, VM3090, VM4090, VN2090 Grape Harvester Service Manual | Publication 84189523B

Order the manual at mid-west-tech.com >

REPAIR MANUAL

CONTENTS

Section	Description
	Specifications
00	Maintenance
05	Machine arrangement
10	Engine
29	Hydrostatic transmission
33	Brakes
35	Hydraulic system
39	Frame
41	Steering
44	Wheels
50	Cab
55	Electrical system
58	Harvesting equipment
60	Product feeding
74	Cleaning
80	Hoppers
88	Accessories

84189523B - 01 - 2010

MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >

SPECIFICATIONS

Chapter 1

CONTENTS

Section	Description	Page
	Machine identification data	3
	Dimensions	4
	Main specifications, from VL6040 to 6090, VM4090	10
	Harvesting equipment main specifications, from VL6040 to 6090, VM4090	13
	Main specifications, from VL5090,5080, 5060; VM3080, 3080H, VN2090	17
	Harvesting equipment main specifications, VL5090,5080, 5060 VM3080, 3080H VN2090	21

VM 3080H = High version

84189523B - 01 - 2010

MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >

SECTION 00 - MAINTENANCE

Chapter 1

CONTENTS


Section	Description	Page
	Lubricant and liquid capacities	2
	Thermal engine maintenance	3
	Harvesting equipment greasing point location	5
	Machine washing	9
	Hydrostatic and hydraulic system maintenance	13
	Routine maintenance and winter storage	15

MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >

HOSE FITTING FASTENING

(Disassembly operations 54. ÷ 55.)
For version
F4GE0484C*D601 by 94 kW (128 HP)


- Fasten the plate (4), the hose (2) and tighten the fastening screws (1, 3 and 5).



119

For versions
F4GE0684C*D600 by 129 kW (175 HP)
F4GE0684E*D600 by 120 kW (160 HP)
F4GE0684G*D600 by 107 kW (145 HP)

Carry out the operations relevant to the previous figure.




120

OIL SUMP FASTENING

(Assembly operation 53.)
For version
F4GE0484C*D601 by 94 kW (128 HP)


- Place the new gasket on the crankcase.
- Install the oil sump (1) and the fastening plate (3).
- Fit the screws (2) and tighten them to the torque prescribed on page 15.



121

For versions
F4GE0684C*D600 by 129 kW (175 HP)
F4GE0684E*D600 by 120 kW (160 HP)
F4GE0684G*D600 by 107 kW (145 HP)

Carry out the operations relevant to the previous figure.




122


MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >

B01 / 10

POSITION OF THE GROUNDS UNDER THE ELECTRIC CABINET BEHIND THE CAB WITHOUT ROPS




POSITION OF THE CABLES IN THE CAB REAR RIGHT ANGLE



MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >


Fig. 1



MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >


B01 / 10

Cab with ROPS



MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >

Connection



MidWestTech | New Holland VL5060, VL5080, VL5090, VL6040, VL6050, VL6060, VL6... Order the manual at mid-west-tech.com >