
SIMON AERIALS INC.
10600 W. Brown Deer Road
Milwaukee, Wisconsin 53224
Phone (414) 355-0802
TWX: 910-262-3310
FAX: (414) 355-0832
Cable: SIMON MIL

SIMON

SERVICE MANUAL

MODEL
MP

HYDRAPORT
after 1 Jan. 1994



Art # A00.00009E

PART NO. 89-100207


Revision "0.2"
September, 1994

MidWestTech | Terex Simon MP Hydraport Boom Lift Service Manual | Publication 89_100207_JAN94
Order the manual at mid-west-tech.com >

Service Manual Table Of Contents

SECTION NAME	SEC. NO.
ADJUSTMENTS	1
LUBRICATION	2
HYDRAULIC FLUID RECOMMENDATIONS & MAINT.	3
HYDRAULIC PUMP OPERATION (HYDRAPORT)	4
TROUBLE SHOOTING CHARTS	5
MISC. TROUBLE SHOOTING	6
HYDRA-PORT CIRCUIT	7
BOOM LIFT CIRCUIT	8
BOOM EXTEND CIRCUIT	9
BOOM SWING CIRCUIT	10
VEHICLE DRVIE CIRCUIT	11
VEHICLE STEER CIRCUIT	12
PLATFORM LEVELING CIRCUIT	13
PLATFORM ROTATE CIRCUIT	14
EMERG. PUMP & VALVE BANK MANIFOLD CIRCUIT	15
EMERGENCY DESCENT CIRCUIT (OPTION)	16

MidWestTech | Terex Simon MP Hydraport Boom Lift Service Manual | Publication 89_100... Order the manual at mid-west-tech.com >



Order the manual at mid-west-tech.com >