
SIMON AERIALS INC.
10600 W. Brown Deer Road
Milwaukee, Wisconsin 53224
Phone (414) 355-0802
TWX: 910-262-2310 •
FAX: (414) 355-0832
Cable: SIMON MIL

CONSTRUCTOR AT40C

SIMON

SERVICE MANUAL



89-444007

REVISION B


MidWestTech | Terex Simon Constructor AT40C Articulated Boom Lift Service Manual | Publication 89_444007_B
Order the manual at mid-west-tech.com >

TABLE OF CONTENTS

INTRODUCTION 2
MACHINE SPECIFICATIONS 3
PRIMARY COMPONENTS 4
COMPONENT LOCATOR UNDERCARRIAGE 5
COMPONENT LOCATOR SUPERSTRUCTURE 6
COMPONENT LOCATOR PLATFORM 7
LUBRICATION CHART / DIAGRAM 8
HYDRAULIC FLUID RECOMMENDATIONS & MAINTENANCE 10
HYDRAULIC SYSTEM 12
HYDRAULIC PUMPS 12
HYDRAULIC MANIFOLD 13
HYDRAULIC OIL TANK 16
BOOM LIFT SYSTEM 16
BOOM EXTEND SYSTEM 18
SWING SYSTEM 19
VEHICLE STEER SYSTEM 21
PLATFORM LEVELING CIRCUIT 22
PLATFORM ROTATE CIRCUIT 23
VEHICLE DRIVE SYSTEM 24
DRIVE SYSTEM CONTROL CIRCUIT 26
EMERGENCY SYSTEM AND PROCEDURES 32
ELECTRICAL SYSTEM 34
MECHANICAL 38
TROUBLESHOOTING 48
MAINTENANCE SCHEDULE 51
MAINTENANCE CHART 63

MidWestTech | Terex Simon Constructor AT40C Articulated Boom Lift Service Manual | Pu... Order the manual at mid-west-tech.com >

MidWestTech | Terex Simon Constructor AT40C Articulated Boom Lift Service Manual | Publication 89_444007_B



Order the manual at mid-west-tech.com >