
SERVICE MANUAL

W40XT(A218), W45XT(A/B215), T5XT(E142)



FORM 897465 Rev. 11/03

MidWestTech | Hyster W40XT(A218), W45XT(A/B215), T5XT(E142) Electric Pallet Jack Ser... Order the manual at mid-west-tech.com >

W40XT(A218), W45XT(A/B215), T5XT(E142)
SERVICE MANUAL CONTENTS

Section	SRM Number	Rev Date
FRAME	0100 SRM 0009	10/00
DC MOTOR MAINTENANCE	0620 SRM 0294	08/03
MASTER DRIVE UNIT (W40XT, W45XT)	0630 SRM 0507	10/96
MASTER DRIVE UNIT	0630 SRM 0533	10/00
STEERING MECHANISM (W40XT, W45XT)	1600 SRM 0508	11/96
STEERING MECHANISM	1600 SRM 0534	10/00
BRAKES (W40XT, W45XT)	1800 SRM 0509	11/96
BRAKES	1800 SRM 0535	02/03
WALKIE HYDRAULIC SYSTEM	1900 SRM 0278	10/00
CURTIS TRANSISTOR MOTOR CONTROLLER	2200 SRM 0411	09/00
ELECTRICAL SYSTEM	2200 SRM 0554	08/99
INDUSTRIAL BATTERY	2240 SRM 0001	11/03
BATTERY INDICATORS	2260 SRM 0138	06/02
LIFTING MECHANISM (W40XT, W45XT)	4000 SRM 0510	11/96
LIFTING MECHANISM	4000 SRM 0536	10/00
INCH (SAE) and METRIC FASTENERS	8000 SRM 0231	03/03
DIAGRAMS WITHOUT ELM	8000 SRM 0457	02/97
CAPACITIES and SPECIFICATIONS (W40XT, W45XT)	8000 SRM 0511	11/96
CAPACITIES and SPECIFICATIONS	8000 SRM 0530	11/93
PERIODIC MAINTENANCE	8000 SRM 0627	10/96
DIAGRAMS WITH ELM	8000 SRM 0686	12/99

PART NO. 897465
Rev. 11/03

MidWestTech | Hyster W40XT(A218), W45XT(A/B215), T5XT(E142) Electric Pallet Jack Ser... Order the manual at mid-west-tech.com >