
FALCON
2548
VERTICAL LIFT

SERVICE
MANUAL

Genie®
A TEREX COMPANY

For Service Concerns Only:
Direct Phone Line to
Service Department,
8:00 AM to 5:00 PM
Central Time,
Monday thru Friday.

Phone (414) 355-3181



Art #A00.00029 E

Part No. 89-755007 • Initial Issue, dated December, 1992 •

MidWestTech | Terex Genie Falcon 2548 Vertical Boom Lift Service Manual | Publication 89_755007

Order the manual at mid-west-tech.com >

Table of Contents

Introduction iii
Machine Specifications iv
Primary Machine Components v
Undercarriage Components vii
Lubrication Chart viii
Lubrication Diagram ix

Section 1: Transportation and Emergency Procedures

Transporting the Unit 1-3
Moving of the Falcon 2548 1-3
Fork Lifting of the Falcon 2548 1-3
Truck Transport of the Falcon 2548 1-3
Unloading Procedures 1-4
Emergency System and Procedures 1-5
Emergency Lowering 1-5
Emergency Drive 1-5
Emergency Procedures 1-6

Section 2: Hydraulic System

Hydraulic Fluid 2-3
Handling Precautions 2-3
Fluid Recommendations 2-3
Hydraulic Fluid Analysis 2-3
System Flushing Procedure 2-4
Hydraulic System Components 2-5
Hydraulic Fluid Reservoir 2-5
Hydraulic Pump 2-5
Control Valve Assembly 2-5
Drive/ Lift and Steer Relief Valves 2-5
Lift Valve 2-6
High Speed Drive Valve 2-6
Directional Drive Valve 2-6
Steer Valve 2-7
Counterbalance Valves (Drive) 2-7
Brake Release Needle Valve 2-7
Check Valves 2-7
Lowering Valve 2-7
Cylinders 2-7
Drive Motors 2-7
Hydraulic System Functional Description 2-8

MidWestTech | Terex Genie Falcon 2548 Vertical Boom Lift Service Manual | Publication 8... Order the manual at mid-west-tech.com >

Electrical System

Battery 3-3
Battery Maintenance (In Storage) 3-3
Battery Maintenance (In Use) 3-3
Battery Preventive Maintenance 3-4
Battery Replacement 3-4
Battery Charger 3-4
Battery Charger Troubleshooting 3-5
Movement Alarm (Optional) 3-5
Tilt Alarm (Optional) 3-5
Tilt Alarm Test 3-5
Tilt Alarm Adjustment 3-5
Descent Alarm 3-6
Automatic Warning Beacon (Optional) 3-6
Relays 3-6
Electric Motors 3-6
Emergency Stop Buttons 3-6

Mechanical Components

Undercarriage 4-3
Tires 4-3
Changing Tires 4-3
Wheels and Lug Nuts 4-3
Front Hub Assembly 4-4
Repacking Front Wheel Bearings 4-4
Drive Motors 4-4
Steer Cylinder Seal Replacement 4-4
Brake Cylinder Seal Replacement 4-5
Hoses and Cables 4-5
Boom 4-5
Boom Lift Cylinder 4-5
Boom Lift Cylinder Removal 4-6
Boom Lift Cylinder Replacement 4-6
Boom Lift Cylinder Seal Replacement 4-7
Boom and Parallel Arm Pivot Pin Replacement 4-7
Boom and Parallel Arm Pivot Pin Bushing Replacement 4-8
Lift Cylinder Holding Valve Replacement 4-8
Cushion Cylinder Replacement 4-8


Troubleshooting

General Troubleshooting Tips 5-3
Troubleshooting Chart 5-4

Index

Appendix

MidWestTech | Terex Genie Falcon 2548 Vertical Boom Lift Service Manual | Publication 8... Order the manual at mid-west-tech.com >



Order the manual at mid-west-tech.com >