584C, 585C, 586C Forklift


Service Manual

9-66631

MidWestTech | Case 584C, 585C, 586C Forklift Service Manual | Publication 9-66631

Order the manual at mid-west-tech.com >

STEP 144



Install shift lever rubber dust cover.

STEP 145



Install a new shift cover gasket.

STEP 146




Install shift cover assembly, making sure forks engage sliding gear and synchronizer assembly.

STEP 147



Install cover retaining bolts and lockwashers. Torque bolts 35 to 42 ft. lbs.



MidWestTech | Case 584C, 585C, 586C Forklift Service Manual | Publication 9-66631

Order the manual at mid-west-tech.com >