ILLUSTRATED PARTS LIST

KUBOTA

ZD21F

ZERO TURN MOWER



Kubota

Order the manual at mid-west-tech.com >

SPEED CONTROL LEVER LH

↔ Interchangeable; ≠ not interchangeable; ← new for old; → old for new

REF.No	Part No.	Description	Q'ty	S.No.	I/C	REMARKS	Weight (kgf)	Weight (lb)
010	K3111-21530	BEARING	2				0.02	0.044
020	K3111-42750	DAMPER	1				0.16	0.352
030	K1211-91120	RUE RING COTTER	2				0.001	0.0022
040	75599-32012	WASHER PLAIN	2				0.002	0.0044
050	K3111-42350	SHAFT SPEED LH	1				0.89	1.958
060	K3111-42412	WASHER SPEED	1				0.01	0.022
070	K3111-42330	ROD SPEED LH	1				0.52	1.144
080	K3111-42440	BOLT REAMER	1				0.014	0.0308
090	K5112-72840	NUT LOCK	1				0.005	0.011
100	75599-32012	WASHER PLAIN	1				0.002	0.0044
110	K3111-42460	LEVER SPEED LH	1				0.85	1.87
120	01053-50825	BOLT	2	<=48263			0.014	0.0308
120	01123-50825	BOLT	2	>=48264	←		0.013	0.0286
130	75599-33012	WASHER SPRING	2	<=48263			0.002	0.0044
140	K3111-42370	GRIP SPEED	1				0.168	0.3696
150	K3111-42480	BOLT STOPPER	1				0.032	0.0704
160	02018-50100	NUT	1				0.011	0.0242
170	K3111-42520	BOOT SPEED CHANGE	1				0.44	0.968
180	K3111-42570	PLATE BOOT	1				0.16	0.352
190	K5112-72840	NUT LOCK	4				0.005	0.011
200	K3151-55710	HOLDER CUP	1				0.22	0.484
210	K3151-55720	STAY CUP HOLDER	1				0.35	0.77
220	03004-50610	SCREW WITH WASHER	3				0.004	0.0088
230	K1122-57140	SCREW TAPPING	3				0.002	0.0044

MidWestTech | Kubota ZD21F Zero Turn Mower Parts Manual | Publication ZD21F Order the manual at mid-west-tech.com >

CONTROL VALVE [COMPONENT PARTS]

↔ Interchangeable; ≠ not interchangeable; ← new for old; → old for new

REF.No	Part No.	Description	Q'ty	S.No.	I/C	REMARKS	Weight (kgf)	Weight (lb)
010	K3111-36652	ASSY VALVE CONTROL	1				2.6	5.72
020	K3111-36540	ASSY BODY	1				1.99	4.378
030	05411-00620	PIN SPRING	1				0.002	0.0044
040	31351-37930	SEAT RELIEF VALVE	1				0.02	0.044
050	31351-37940	POPPET	1				0.005	0.011
060	37410-37330	SPRING	1				0.01	0.022
070	67156-36660	SHIM ADJUSTING	2			0.3mm	0.001	0.0022
070	67156-36670	SHIM ADJUSTING	1			0.8mm	0.002	0.0044
070	67156-36680	SHIM ADJUSTING	1			0.2mm	0.001	0.0022
080	K3111-36530	PLUG	1				0.029	0.0638
090	66101-36370	SPRING SPOOL RETURN	1				0.01	0.022
100	66101-36360	COVER RELIEF	1				0.06	0.132
110	K3111-36570	GASKET	1				0.001	0.0022
120	01202-50622	BOLT	4				0.007	0.0154
130	66591-36430	COVER VALVE	1				0.18	0.396
140	K3311-36350	SHAFT CONTROL VALVE	1				0.093	0.2046
150	04811-00100	O RING	1				0	0
150	04816-00100	O RING	1		←		0.001	0.0022
160	66591-36450	ARM VALVE GUIDE	1				0.05	0.11
170	04111-50060	WASHER	1				0.001	0.0022
180	66591-36480	BOLT	1				0.004	0.0088
190	66591-36463	BOLT	1				0.05	0.11
200	04714-00300	GASKET	1				0.002	0.0044
210	62061-18270	SPRING STOPPER	1				0.003	0.0066
220	07715-00803	BALL	1				0.004	0.0088
230	66905-36470	GASKET	1				0.002	0.0044
240	04512-60060	WASHER SPRING	4				0.001	0.0022
250	01053-50665	BOLT	2				0.015	0.033
260	01053-50650	BOLT	2				0.011	0.0242

MidWestTech | Kubota ZD21F Zero Turn Mower Parts Manual | Publication ZD21F Order the manual at mid-west-tech.com >

↔ Interchangeable; ≠ not interchangeable; ← new for old; → old for new

REF.No	Part No.	Description	Q'ty	S.No.	I/C	REMARKS	Weight (kgf)	Weight (lb)
010	K3151-56312	ASSY SUSPENSION SEAT	1	<=50342			17	37.4
010	K3151-56313	ASSY SUSPENSION SEAT	1	>=50343	←		17	37.4
020	K3111-56128	BASE SUSPENSION	1	<=50342		NOT SALE.ORDER BY Ref.No.260	6.4	14.08
020	K3111-56190	BASE SUSPENSION	1	>=50343	≠		0	0
030	K3111-56470	GROMMET	1				0.001	0.0022
040	K3151-56413	COVER CENTER RH	1				0.7	1.54
050	01754-50820	BOLT FLANGE	3				0.015	0.033
060	K3151-56422	COVER CENTER LH	1				0.72	1.584
070	01754-50820	BOLT FLANGE	3				0.015	0.033
080	K3111-56150	LINK SUSPENSION F	1	<=50342			0.4	0.88
080	K3111-56152	LINK SUSPENSION F	1	>=50343	≠		0.4	0.88
090	K3111-56180	LINK SUSPENSION R	1	<=50342			0.77	1.694
090	K3111-56183	LINK SUSPENSION R	1	>=50343	≠		0.77	1.694
100	K3111-56160	SPACER SUSPENSION	4	<=50342			0.007	0.0154
100	K3111-56162	SPACER SUSPENSION	4	>=50343	≠		0.007	0.0154
110	K3111-56210	BUSH	4	<=50342			0.005	0.011
110	K3111-56280	BUSH	4	>=50343	≠		0.006	0.0132
120	01053-50830	BOLT	4	<=50342			0.015	0.033
120	01133-51035	BOLT	4	>=50343	≠		0.03	0.066
130	75599-33012	WASHER SPRING	4	<=50342			0.002	0.0044
140	K5112-72830	WASHER PLAIN	4	<=50342			0.005	0.011
140	75599-32113	WASHER PLAIN	4	>=50343	≠		0.01	0.022
150	K3111-56220	BUSH	4				0.01	0.022
160	02054-50080	NUT	4	<=50342			0.005	0.011
160	02118-50100	NUT	4	>=50343	≠		0.005	0.011
170	K3111-56235	SHAFT ADJUSTER	1				0.24	0.528
180	K3111-56240	HANGER SPRING	1				0.225	0.495
190	75599-32114	WASHER PLAIN	1				0.011	0.0242
200	75599-52310	PIN SPRING	1				0.001	0.0022
210	K3111-56480	NUT LEFT-HAND	4				0.012	0.0264
220	K3111-56250	SPRING SUSPENSION	2				0.415	0.913
230	K2561-36310	GRIP	1				0.04	0.088
240	K3111-56450	RUBBER BUMPER	4				0.01	0.022
250	K3111-98422	MANUAL	1	<=50342		NOT SALE	0	0
260	K3111-98412	KIT SEAT	1	<=50342			1.95	4.29

MidWestTech | Kubota ZD21F Zero Turn Mower Parts Manual | Publication ZD21F Order the manual at mid-west-tech.com >